



Public Notice

Hay River Recovery Update
Sunday May 22, 2022 – 4:45pm

Lift Station #1 is now operational with reduced installed capacity and contingency. Several auxiliary systems within the building will need to be repaired and replaced in the coming months. The lift station will be continually monitored this week.

Water services will be restored through a phased opening. There may be intermittent interruptions during the opening. Residents are asked to initially conserve water and gradually resume normal water usage over the next 24 hours. **Estimated restoration time is between 6:30pm and 7:30pm, Sunday May 22.**

Wastewater piping and manholes have been hydrovaced to remove sediment in preparation of resumption of wastewater services to the impacted zones.

Property owners should monitor their basements upon service restoration to ensure no wastewater backups occur as well as ensure water taps have not been left open. A boil water advisory remains in place for Hay River – some slight discoloration of water is expected.

If you encounter unexpected issues with water or service please contact the Public Works department at 867-875-7137.

Thanks to our local electrical and mechanical contractors and members of the Public Works department who have worked tirelessly to restore the lift station services to date.

Zone Summaries

Green Zones – All utility and infrastructure systems functional

- Mile 5
- McRorie Rd. South through Miron Drive.
- McRorie Rd. to West Channel Bridge east of highway #2
- Corridor (excluding Paradise Gardens)
- 553 including Saskatoon and Cranberry
- Industrial Area
- West Channel Bridge to Airport
- Downtown Core and Highway Commercial between Northwestel and Boardroom Restaurant
- Old Town

- West Channel

Yellow Zones - One utility or infrastructure system compromised.

- None

Orange Zones - Multiple utility and infrastructure systems non-functional.

No trucked water or sewer service until road accessible by heavy vehicles.

- Paradise Gardens
 - Considerable damage to over 1km of road surface with bank erosion and undercutting of bank. Impassable in some sections.
 - Power distribution network is online. Some properties require electrical inspections.